

ASSEMBLY DRAWING


1




2




3




4



5



6



Ax1 	Bx1 	Cx2 
Dx1 	Ex1 	Fx5 
Gx6  M6x35mm	Hx3  M8x40mm	Ix6  M6x25mm
Jx1 	Kx1 	Lx1 
Mx1 	Nx1 	Ox6 
Px2 	Qx1 	Rx4  M6x25mm
		Sx2  M6x12mm